

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

USEPA: Z 355 729 113

MDNR: Z 355 729 114

October 25, 1996

Mr. Duane Heaton
Remedial Project Manager
CERCLA Enforcement Section
U.S. Environmental Protection Agency
230 S. Dearborn Street
Chicago, IL 60604

Mr. Oladipo Oyinsan, Supervisor
Michigan Department of Natural Resources-ERD
38980 Seven Mile Road
Livonia, MI 48152


Subject: BASF Riverview Site Inspection Report

To whom it may concern:

Please find enclosed the Fall inspection report for the BASF Riverview Site as required by Consent Decree No. 80-73699 of July, 1984.

If there are any questions, please contact me.

Very truly yours,


Douglas P. Thiel
Manager, Quality and Ecology Services

enc

Z:DIEMRIVISPR.DOC



ENVIRONMENTAL

PREVENTIVE MAINTENANCE

BASF Corporation
TITLE: RIVERVIEW PROPERTY

PREPARED BY: GERLACH

DATE ISSUED/REVISED: 04/03/95
CURRENT WORK ORDER: 1051672

CC No.: 30580
INSPECTION FREQUENCY: SEMI-ANNUALLY
INSPECTION DUE 09/24/96

Folder No.: 1490M6.RTE
SHEET 1
Eq Code: 3058000-00

PROCEDURE

REPORT HERE - FINDINGS &
ITEMS REPAIRED OR REQUIRED

FOLDER NUMBER: 1490M6.RTE
Inspection Date: 10/5/96
AGENCY REPORT IS DUE WITHIN TWO WEEKS AFTER INSPECTION.
UPON REVIEW AND APPROVAL, RETURN THIS PM TO ECOLOGY FOR PREPARATION OF PRINTED REPORT AND FILING BY SITE ENGINEER.
This PM requires the inspector to look at many things and walk or drive over a large area. The inspector should completely prior to making the inspection so that no wasted effort has to occur "Going Back".

Agency Report Date: 10/25/96

I. Inspect entire fence.

I.A. Make a list of any broken
barbed wire, broken or de-
formed fence, bent or dam-
aged fence posts or rails,
gate hinges, locks, etc.

A. Fence must be completely intact, including 3 strands of
barbed wire on top. All gates must be locked.

Observation: Okay

Response:

B. Inspect signs on fence. Signs must face outward from
property. The signs must be spaced at 100' intervals on
all four sides of the property. The signs must be in
good condition with 1-1/2" high letters.

I.B. 1. Are signs spaced every
100 ft.? Yes ☒ No ☐

2. Make a list of missing,
rusted, bent, illegible,
etc., signs.

WARNING
KEEP OUT
MANAGED INDUSTRIAL WASTE DISPOSAL AREA

Observation: Okay

Response:

II. Inspect vegetation from Jefferson/to the water and from the
common property line with Firestone to the municipal ramp.

A. Look for any "bare" areas (spots or areas which do not
have plant life growing).

II.A. List "bare" areas. Describe
size and location of bare
spot.

Observation: None

Response:

ENVIRONMENTAL

FOLDER NO.: 1490M6.RTE

SHEET 2

B. Measure the height of the vegetation. As the vegetation is measured, look for areas where growth is stunted.

Observation: 2 1/2"

Response: _____

II.B. List the "average" height of the vegetation.

III. Inspect the shoreline for stability.

Observation: Okay

Response: _____

III. List any shoreline erosion, washing, other deterioration or accumulation of debris.

IV. Review the integrity of the compacted clay cover.

A. Inspect the entire area for the physical condition of the surface.

Observation: Okay

Response: _____

IV.A. List any erosion, standing pools of water, weathering, change in drainage patterns, etc.

B. Look for any deep-rooted vegetation (trees or other plant life which might or does have tap roots). Any vegetation which is taller than surrounding vegetation should be considered deep-rooted.

Observation: None

Response: _____

IV.B. List deep-rooted vegetation.

V. Inspect the berm which is constructed along the common property line with Firestone. This berm is constructed to eliminate water flowing from the Firestone property onto the site.

Ground hog observed entering Den dug into berm approx. 200 feet west of Detroit River

V. Is the berm at least 6 inches above the level of the Firestone property at the property line?
Yes X No

Is there any evidence of water flowing from the Firestone property onto the site?
Yes No X

ENVIRONMENTAL

FOLDER NO.: 1490M6.RTE

SHEET 3

VI. Inspect the two concrete drainage ditches on the site, one through the center and one at the northeast corner.

A. Look at overall condition of the ditches.

General sedimentation of approx. 1 inch, from segment, 24 through segment #1.

Observation: _____

Response: _____

B. There are thirty (30) joints in the center ditch. Note condition of each joint. Is joint in place or is it protruding above the surface of the concrete? Is the joint leaking? If there is standing water at the joint, is it clear or off color?

Joint 2:
Observation: Okay

Response: _____

Joint 4:
Observation: Okay

Response: _____

Joint 6:
Observation: Erosion/Bare patches on south side of segment.

Response: will take out & seal by 4/15/97

Joint 8:
Observation: Beginning of spalling/cracking of concrete.

Response: Repair by 4/15/97

Joint 10:
Observation: Okay

Response: _____

VI.A. List any cracks in the concrete, leaking through the cracks, accumulated debris, standing water, etc.

Joint 1:
Observation: Okay

Response: _____

Joint 3:
Observation: Okay

Response: _____

Joint 5:
Observation: Erosion/Bare patches on south side of segment.

Response: Re-seal 4/15/97

Joint 7:
Observation: Beginning of spalling/cracking of concrete.

Response: Repair by 4/15/97

Joint 9:
Observation: Spalling/cracking of concrete on east side of segment.

Response: Repair by 4/15/97

Joint 11:
Observation: Okay

Response: _____

ENVIRONMENTAL

FOLDER NO.: 1490M6.RTE

SHEET 4

VI. B. (Cont'd.) There are thirty (30) joints in the center ditch. Note condition of each joint. Is joint in place or is it protruding above the surface of the concrete? Is the joint leaking? If there is standing water at the joint, is it clear or off color?

Joint 13:
Observation: Loose/cracking grout
between segments 12, 13, 14
Response: Repair by 4/15/97

Joint 15:
Observation: Okay
Response: _____

Joint 17:
Observation: Loose caulking in crack
on south side of segment.
Response: Repair by 4/15/97

Joint 19:
Observation: Erosion/Bare spot on
north edge of segment.
Response: Re-seed by 4/15/97

Joint 21:
Observation: Okay
Response: _____

Joint 23:
Observation: Okay
Response: _____

Joint 25:
Observation: Okay
Response: _____

VI.B. List condition of each joint.

Joint 12:
Observation: Severe spalling/
cracking of segment.
Response: Repair 4/15/97

Joint 14:
Observation: Okay
Response: _____

Joint 16:
Observation: Okay
Response: _____

Joint 18:
Observation: Okay
Response: _____

Joint 20:
Observation: Erosion/Bare spot
on north edge of segment.
Response: Re-seed 4/15/97

Joint 22:
Observation: Okay
Response: _____

Joint 24:
Observation: Okay
Response: _____

Joint 26:
Observation: Loose caulking in
segment joint.
Response: Repair 4/15/97

ENVIRONMENTAL

FOLDER NO.: 1490M6.RTE

SHEET 5

VI. B. (Cont'd.) There are thirty (30) joints in the center ditch. Note condition of each joint. Is joint in place or is it protruding above the surface of the concrete? Is the joint leaking? If there is standing water at the joint, is it clear or off color?

Joint 27:
Observation: Okay

Response: _____

Joint 29:
Observation: Okay

Response: _____

There are four (4) joints in the north ditch. Note condition of each joint. Is joint in place or is it protruding above the surface of the concrete? Is the joint leaking? If there is standing water at the joint, is it clear or off color?

Joint B:
Observation: Good

Response: _____

VII. Inspect each of the nine (9) monitoring wells for integrity.

VI.B. List condition of each joint.

Joint 28:
Observation: Okay

Response: _____

Joint 30:
Observation: Okay

Response: _____

Joint A:
Observation: Good

Response: _____

Joint C:
Observation: Good

Response: _____

Joint D:
Observation: Good

Response: _____

VII. List any problems with the wells.
Observation: _____

Response: _____

ENVIRONMENTAL

FOUNDER NO.: 1490M6.RTE

SHEET 6

Upon completion of this PM, it must be routed for signature/comments as indicated on page 1.

Inspected by: *Jessie B. Warr* Date Inspected: *10/15/96*
PM Reviewed and Response initiated by: *John S. Kiefer* Date: *10/23/96*
***** END ***** END ***** END ***** END ***** END ***** END ***** END *****